

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY  
DIVISION OF WATER POLLUTION CONTROL  
PERMIT SECTION  
Springfield, Illinois 62706

RECEIVED

APPLICATION FOR MINE RELATED POLLUTION CONTROL PERMIT

WPC-PS-MM

AUG 23 1976

ENVIRONMENTAL PROTECTION AGENCY  
DIV. OF WATER POLLUTION CONTROL  
RECORDS UNIT - SPRINGFIELD  
STATE OF ILLINOIS

1. NAME AND LOCATION:

1.1 Applicant is a (check one):

i. ☒ sole proprietorship, ii. ☐ joint venture iii. ☐ partnership, or iv. ☒ corporation

1.2 Name of Applicant Freeman United Coal Mining Company

Address 300 W. Washington St., Chicago, Illinois Phone # 312-263-2800

1.3 Mine Name Fidelity Mine #11

County Perry

Local Mine Address DuQuoin, Illinois 62832 Phone # 618-542-2116

1.4 Superintendent or Local Contact Person Oscar Ernst

Address Fidelity Mine #11 DuQuoin, Illinois 62832 Phone # 618-542-2116

1.5 Mine Location

1.5.1 22,23,26,27 6S 2W 3RD  
Sections Township Range P.M.

Sections Township Range P.M.

1.5.2 Name, distance, and direction of nearest incorporated town DuQuoin, 2½ miles - SW

1.5.3 Other location information

2. BRIEF DESCRIPTION OF PROJECT OR FACILITIES COVERED BY THIS APPLICATION:

See Attached Letter

3. This is an Application for: Opening \_\_\_\_\_; Reopening \_\_\_\_\_; Operating \_\_\_\_\_;  
Abandoning \_\_\_\_\_; or Supplemental Permit ☒ \_\_\_\_\_; for a mine \_\_\_\_\_ or mine refuse area \_\_\_\_\_.  
If this is an Application for Supplemental Permit, give original Permit # 1973-MD-8-09  
and date \_\_\_\_\_.

4. DOCUMENTS BEING SUBMITTED:

4.1 Submit the corresponding schedule for the items which this application involves, and check the appropriate spaces.

Opening or Reopening a Mine  
Operating a Mine  
Mine Refuse Disposal  
Abandonment of a Mine  
Discharges Location and Characteristics

MA \_\_\_\_\_  
MB ☒ \_\_\_\_\_  
MC \_\_\_\_\_  
MD \_\_\_\_\_  
ME \_\_\_\_\_

4.2 List of Other Documents Submitted:

A. Map of area to be mined

B.

C.

D.

E.

EPA Region 5 Records Ctr.



324276